



* Designates those parts included in repair kit #229850

REPLACEMENT PARTS

MODEL NO.
72000D/EI

CAPACITY
1 1/2 TON

DESCRIPTION
TRANSMISSION JACK

2023



| INDEX NO. | DESCRIPTION | PART NO. | REQ'D NO. |
|-----------|----------------------|----------|-----------|
| 1 | Frame Assembly | N/A | 1 |
| 2 | Lift Arm Assembly | N/A | 1 |
| 3 | Guide Arm | 229227 | 2 |
| 4 | Trunion | 229223 | 1 |
| 5 | Trunion Arm | 229224 | 2 |
| 6 | Trunion Arm Rivet | 229226 | 2 |
| 7 | Pivot Pin | 229222 | 1 |
| 8 | Chain Tensioner | 229299 | 1 |
| 9 | Extension Arm | 229301 | 4 |
| 10 | Lock Screws | 229302 | 4 |
| 11 | Bolt | 11013 | 4 |
| 12 | Bolt | 11179 | 4 |
| 17 | "E" Retaining Ring | 12139 | 4 |
| 18 | Fore/aft Tilt Pin | 229026 | 1 |
| 19 | Saddle Base Plate | 229303 | 1 |
| 20 | Washer | 229061 | 1 |
| 21 | Nut | 229062 | 1 |
| 25 | Saddle Base Assembly | 229060 | 1 |
| 26 | Rear Side Tilt Screw | 229066 | 2 |
| 28 | Pivot Bolt | 229059 | 1 |

| INDEX NO. | DESCRIPTION | PART NO. | REQ'D NO. |
|-----------|--------------------------------|----------|-----------|
| 29 | Front Side Tilt Screw | 229064 | 2 |
| 30 | Complete Tilt Screw Assembly | 45101151 | 1 |
| 33 | Saddle Base Clevis | 229019 | 1 |
| 34 | Retaining Ring | 12141 | 4 |
| 36 | Retaining Ring | 229077 | 2 |
| 38 | Grease Zerk Fitting | 209048 | 1 |
| 39 | Guide Arm Screw | 209052 | 2 |
| 40 | Caster Mounting Bolt | 209133 | 8 |
| 41 | Cotter Pin | 209043 | 1 |
| 42 | Cotter Pin | 209057 | 1 |
| 43 | Caster Mounting Nut | 209124 | 16 |
| 44 | Nut | 209129 | 2 |
| 45 | Lockwasher | 209126 | 2 |
| 46 | Flat Washer | 2016 | 12 |
| 47 | Retaining Ring | 209044 | 1 |
| 48 | 22 mm Snap Ring | 12205 | 2 |
| 49 | Caster Assy. Complete | 229713 | 4 |
| 50 | Complete Hydraulic Power Assy. | 229861 | 1 |
| 51 | Saddle Assy., Complete | 229905 | 1 |

2023

REPLACEMENT
PARTS

MODEL NO.
72000DI/EI

CAPACITY
1 1/2 TON

DESCRIPTION
TRANSMISSION JACK

